

APPENDIX H

PHOTOS OF IMPROVEMENTS




Daylodge looking southwest.



Lodge looking northwest.



Garage building front and east side looking northwest.



Maintenance building front and east end looking northwest.



Maintenance building interior.



West lift lower terminal looking north.



West lift line looking uphill (south) from the base.



East chairlift bottom terminal looking east.



East lift line looking downhill (north) from near the top terminal.